

No	Name	Description	Price
LU-ST-01	Ford Crossflow / Kent / BDA (110 tooth ring gear) 9 tooth / 2 bolt high torque starter motor	Lucas LRS00102 universal fitment - Lucas 9 tooth / 2 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥87,000
LU-ST-02	Ford Crossflow / Kent / BDA (110 tooth ring gear) 9 tooth / 2 bolt WOSP Axial starter motor	Lucas LRS00102 universal fitment - Lucas 9 tooth / 2 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥193,000
LU-ST-03	Ford Crossflow / Kent / BDA (110 tooth ring gear) 9 tooth / 3 bolt high torque starter motor	Lucas LRS00102 universal fitment - Lucas 9 tooth / 3 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥87,000
LU-ST-04	Ford Crossflow / Kent / BDA (110 tooth ring gear) 9 tooth / 3 bolt WOSP Axial starter motor	Lucas LRS00102 universal fitment - Lucas 9 tooth / 3 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥193,000
LU-ST-05	Ford Crossflow / Kent / BDA (110 tooth ring gear) 10 tooth / 2 bolt high torque starter motor	Lucas LRS00102 universal fitment - Lucas 10 tooth / 2 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥87,000
LU-ST-06	Ford Crossflow / Kent / BDA (110 tooth ring gear) 10 tooth / 2 bolt WOSP Axial starter motor	Lucas LRS00102 universal fitment - Lucas 10 tooth / 2 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥193,000
LU-ST-07	Ford Crossflow / Kent / BDA (110 tooth ring gear) 10 tooth / 3 bolt high torque starter motor	Lucas LRS00102 universal fitment - Lucas 10 tooth / 3 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥87,000
LU-ST-08	Ford Crossflow / Kent / BDA (110 tooth ring gear) 10 tooth / 3 bolt WOSP Axial starter motor	Lucas LRS00102 universal fitment - Lucas 10 tooth / 3 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥193,000
LU-ST-09	Triumph 'Various' & Vauxhall VX high torque starter motor	Lucas LRS00101 universal fitment	¥80,000
LU-ST-10	Ford Crossflow / Kent / BDA (110 tooth ring gear) 9 tooth / 2 bolt slimline starter motor	Lucas LRS00102 universal fitment - Lucas 9 tooth / 2 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥94,000
LU-ST-11	Ford Crossflow / Kent / BDA (110 tooth ring gear) 9 tooth / 2 bolt high torque starter motor (+VE Ground)	Lucas LRS00102 universal fitment - Lucas 9 tooth / 2 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥115,000
LU-ST-12	Ford Crossflow / Kent / BDA (110 tooth ring gear) 9 tooth / 3 bolt slimline starter motor	Lucas LRS00102 universal fitment - Lucas 9 tooth / 3 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥94,000
LU-ST-13	Ford Crossflow / Kent / BDA (110 tooth ring gear) 9 tooth / 3 bolt high torque starter motor (+VE Ground)	Lucas LRS00102 universal fitment - Lucas 9 tooth / 3 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥115,000
LU-ST-14	Ford Crossflow / Kent / BDA (110 tooth ring gear) 10 tooth / 2 bolt slimline starter motor	Lucas LRS00102 universal fitment - Lucas 10 tooth / 2 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥97,000
LU-ST-15	Ford Crossflow / Kent / BDA (110 tooth ring gear) 10 tooth / 2 bolt high torque starter motor (+VE Ground)	Lucas LRS00102 universal fitment - Lucas 10 tooth / 2 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥117,000
LU-ST-16	Ford Crossflow / Kent / BDA (110 tooth ring gear) 10 tooth / 3 bolt slimline starter motor	Lucas LRS00102 universal fitment - Lucas 10 tooth / 3 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥97,000
LU-ST-17	Ford Crossflow / Kent / BDA (110 tooth ring gear) 10 tooth / 3 bolt high torque starter motor (+VE Ground)	Lucas LRS00102 universal fitment - Lucas 10 tooth / 3 bolt / 4.5" inertia replacement (110 tooth ring gear)	¥117,000
LU-ST-18	Lucas LRS00101 slimline starter motor	Lucas LRS00101 replacement 'slimline' (5" PCD 2 bolt mount / 9 tooth pinion)	¥101,000
LU-ST-19	Case / David Brown / Massey Ferguson / Perkins 'various' high torque starter motor	Lucas LRS157 / LRS00157 replacement	¥119,000

LU-ST-20	Perkins / Volvo (non insulated) high torque starter motor	Lucas LRS00189 replacement (non insulated)	¥103,000
LU-ST-21	Perkins / Volvo (insulated earth return) high torque starter motor	Lucas LRS00189 replacement (insulated)	¥138,000
LU-ST-22	Karrier PB / DPB diesel '69-'82 high torque starter motor	Lucas LRS00160 replacement	¥119,000
LU-ST-23	Daimler / Jaguar various models high torque starter motor	Lucas LRS00525 / LRT160 replacement	¥84,000
LU-ST-24	Jeep Mahindra CJ540 / Lucas-TVS high torque starter motor	Lucas TVS 26925 165A (26925165A) replacement	¥119,000
LU-ST-25	Case / David Brown / Ford / Heden / New Holland high torque starter motor	Lucas LRS00212, LRS00230, LRS01322, LRS01498, LRS01637 replacement	¥119,000
LU-ST-26	Lucas LRS00101 replacement high performance starter motor	Lucas LRS00101 replacement	¥138,000
LU-ST-27	Ford Crossflow / Kent / BDA (110 tooth ring gear) high performance starter motor	Lucas LRS00102 universal fitment	¥138,000
LU-ST-28	Reliant Fox / Kitten & Rialto high torque starter motor	Lucas LRS00101 Replacment 'Reliant specific'	¥87,000